

TYPE	Telescopic Handler
MAKE	JLG
MODEL	3509
CHASSIS / VIN	YC500001160002762

Report Number	PA 20250324-1212
Date	24-Mar-2025
Created By	Nathan Harrod
Assessor	Nathan Harrod
Assist. Assessor(s)	
Owner	Pickles Auctions Brisbane
Stock Number	61863687
Sale ID	9579
Assessment Purpose	Sale
State	QLD

Pickles

38

✓ RISK TREATMENTS IN PLACE

39

⚠ RISK TREATMENTS REQUIRED



CRITICAL

2

MEDIUM

3

HIGH

34

LOW

0

TABLE OF CONTENTS

SECTION 1

IMPORTANT INFORMATION

Contains information outlining the scope and any limitations applicable to this Risk Management Report

SECTION 2

MACHINE DETAILS

Contains standard machine specifications and details of any extras fitted

SECTION 3

RISK ANALYSIS, RISK EVALUATION & RISK TREATMENT

Contains details of the technique used to calculate risk ratings, time frame and risk treatments. Please refer to this information when reviewing and interpreting the information in section 4 & 5

SECTION 4

RISK TREATMENTS REQUIRED

Contains detailed information regarding the risk treatments to be implemented including hazard, risk rating, time frame, relevant standards & legislative references

SECTION 5

RISK TREATMENTS IN PLACE

Contains detailed information regarding the risk treatments in place including hazard, risk rating, relevant standards & legislative references

SECTION 6

IMAGES AND NOTES

Contains images & any relevant information entered by the assessor

SECTION 1 IMPORTANT INFORMATION

This report generated by Plant Assessor™ © Online Safety Systems on Thursday 27 Mar 2025 1:44 PM

This Risk Management Report has been prepared for -

(insert recipient name/company name)

This document has been prepared to cover the sale or transfer of this item of plant between the Company identified on the front cover and their named recipient. This report must not be used for any subsequent sale or transfer.

This document is provided to meet duty of care obligations as set out in relevant state and territory health and safety regulations for the supply of plant and the sale and transfer of plant.

The safety hazards associated with the operating and maintaining of this item of plant have been identified as far as practical by visual inspection. This item of plant is being sold in an "as-is" condition with known and unknown safety hazards. No physical testing has been conducted (eg. Wire rope tests, stress tests, structural/non-destructive tests, noise tests, vibration tests, brake tests, insulation tests etc.) unless stated otherwise in the notes.

This document is not intended to provide information on, nor warrant the mechanical, electrical or structural condition of this item of plant. Any information on standard features have been supplied through the manufacturer and should be used as a guide only until otherwise verified.

This item of plant should be further assessed, tested and inspected or dismantled as necessary to gauge any further hazards and /or risks relating to SPECIFIC WORKPLACE USE, which are currently unknown, in accordance with relevant standards, regulations and acts.

Under common law and relevant state and territory health and safety acts, regulations and codes of practice, there is a requirement for the plant owner, employer and operator to exercise a duty of care in the safe operation and maintenance of plant. Accordingly before this item of plant is supplied to, or used at any workplace it must be inspected to ensure it is in a fully operational, safe and serviceable condition and that operators and maintenance personnel are appropriately trained in the use & maintenance of this item of plant.

For further information regarding this report contact Online Safety Systems on 1300 72 88 52

SECTION 2 MACHINE DETAILS

- NOISE TEST RESULTS	
1. Manufacturers specified noise level dBA	
2. Ambient noise level dBA	
3. Noise level - Operator position (high idle) dBA	
4. Noise level - Operator position (low idle) dBA	
5. Noise level LHS dBA @ m (high idle)	
6. Noise level Front dBA @ m (high idle)	
7. Noise level RHS dBA @ m (high idle)	
8. Noise level Rear dBA @ m (high idle)	
BOOM	
Boom Lower (seconds)	
Boom Raise (seconds)	
BRAKES	
Brake Type	
BUCKET	
Bucket width (mm)	
CAPACITIES	
Fuel Tank Capacity (Litres)	
Reach with 1t load (mm)	
DIMENSIONS/WEIGHTS	
Dry Weight (kg)	8600 (approx)
Ground clearance (mm)	420
Height (mm)	2450
Length (mm)	5620

DIMENSIONS/WEIGHTS	
Operating weight (kg)	
Turn circle diameter (mm)	
Wheelbase (mm)	
Width (mm)	
DRIVES	
Drive	4x4
ENGINE	
Engine Displacement (Litres)	
Engine Make & Model	Perkins 1104D-44T
Engine Number	
Number of Cylinders	
Power (kW@rpm)	
Power rating RPM	
EXTRAS	
Airconditioning & heating	
ROPS & FOPS	
Stabilisers fitted	
GENERAL	
Air Suspension Seat	
Carrier Rotating Angle (degrees)	
Chassis Type	
Crowd (seconds)	
Dump (seconds)	
Extras	
Extras B	
Front & Rear Brakes	
Front, Rear & Roof Wiper & Washer	
Heaped capacity, 2:1 SAE (m3)	
Hydraulic Attachment Locking	
Park Brake type	
Tele In (seconds)	
Tele Out (seconds)	
Work Lights - Front	
Work Lights Rear	
HYDRAULICS	
Hydraulic Oil Reservoir Capacity (Litres)	
Hydraulic System	
Hydraulics - Flow Rate (l/min) / Pressure (kg/cm2)	
Hydraulics Oil Cooler	
PLANT CLASSIFICATIONS	
Class	
Year	
RETAIL \$	
New Price	
New Price Date	
SAFETY STRUCTURES	
FOPS Compliance No.	
FOPS Serial No.	
ROPS Compliance No.	
ROPS Serial No.	
STEERING	
Steering Angle (degrees)	
Steering system	
TRANSMISSION	
Maximum speed (km/h)	

TRANSMISSION	
Speeds F/R	
Transmission Type	
TYRES	
Tyres - Front & Rear	
WORK CAPABILITIES	
Capacity at maximum reach (kg)	1200kg
Lift capacity maximum height (kg)	
Maximum lift capacity, any height (kg)	
Maximum Lift Height (mm)	
Maximum Reach (mm)	
Reach at maximum height (mm)	
EXTRAS	
Air Conditioning	
FOPS	
ROPS - Cabin	

SECTION 3 RISK ANALYSIS / RISK EVALUATION






RISK ANALYSIS		CONSEQUENCE				
LIKELIHOOD		1. INSIGNIFICANT Dealt with by in house first aid	2. MINOR Treated by medical professionals, hospital out patients	3. MODERATE Significant non permanent injury overnight hospital stay	4. MAJOR Extensive permanent injury eg. Loss of fingers, extended hospital stay	5. CATASTROPHIC Death, permanent disabling injury eg. Loss of hand, quadriplegia
	A. Almost certain to occur in most circumstances	MEDIUM 8	HIGH 16	HIGH 18	CRITICAL 23	CRITICAL 25
	B. Likely to occur frequently	MEDIUM 7	MEDIUM 10	HIGH 17	HIGH 20	CRITICAL 24
	C. Possibly and likely to occur at sometime	LOW 3	MEDIUM 9	MEDIUM 12	HIGH 19	HIGH 22
	D. Unlikely to occur but could happen	LOW 2	LOW 5	MEDIUM 11	MEDIUM 14	HIGH 21
	E. May occur but only in rare circumstances	LOW 1	LOW 4	LOW 6	MEDIUM 13	MEDIUM 15

RISK EVALUATION	CRITICAL	Act immediately to mitigate risk. Implement risk treatment(s) in accordance with the risk treatment table below.
	HIGH	Act immediately to mitigate risk. Implement risk treatment(s) in accordance with the risk treatment table below. If the appropriate risk treatments are not immediately accessible establish interim risk treatment strategies. Permanent risk treatments must be implemented within one week.
	MEDIUM	Take reasonable steps to mitigate and monitor the risk. Implement risk treatment(s) in accordance with the risk treatment table below. Permanent risk treatments must be implemented with one month.
	LOW	Take reasonable steps to mitigate and monitor the risk. Implement risk treatment(s) in accordance with the risk treatment table below. Permanent risk treatments must be implemented with three months.








RISK TREATMENT	Selecting the most appropriate risk treatment option involves balancing the costs and efforts of implementation against the benefits derived, with regard to legal, regulatory and other requirements. (source AS/NZS ISO 31000:2009)	
	Eliminate	Eliminate the risk source.
	Substitute	Provide an alternative that is capable of performing the same task which is safer.
	Engineering	Provide or construct a physical barrier or guard.
	Administration	Develop policies, procedures, practices and guidelines in consultation with employees to mitigate the risk. Provide training, instruction and supervision about the risk source.
	Personal protective	Provide personal protective equipment to protect the individual from the risk source.

SECTION 4 RISK TREATMENTS REQUIRED








This section of the report pertains to hazards created by use of this item of plant which currently do not have risk treatments in place. The risk treatments recommended in this section have been developed based on relevant Australian Standards, health & safety legislation, the hierarchy of risk treatment in accordance with the guidelines set forth in AS/NZS ISO 31000 – Risk Management and various other sources. The recommended risk treatment measures must be developed, implemented and validated as effective prior to the operation, maintenance or testing of this item of plant. Treatments applied must be dated and initialled adjacent the recommendations. All operators must read and understand the entire contents of this section prior to operating this item of plant.







HAZARD(S)	Prelim. Risk Rating	Residual Risk Rating	Time Frame	Due Date	Date Rectified	Initial
 INCORRECT OPERATION	CRITICAL 24	MEDIUM 15	Immediate	24-Mar-25		
<p>Risk Treatment Required: Operator Competency</p> <p>Only persons who are qualified, trained and experienced and/or hold the relevant certification/license can operate this item of plant. If there is not a competent/licensed person available for operation of this item of plant then only persons who are supervised by a competent/licensed person can operate this item of plant.</p> <p>Legislation: State Health & Safety Legislation & Regulation</p> <p>References: Occupational Health & Safety Act & Regulations, Work Health & Safety Act & Regulations-</p>						
 INCORRECT OPERATION, NON COMPLIANCE	CRITICAL 24	MEDIUM 15	Immediate	24-Mar-25		
<p>Risk Treatment Required: Attachment Controls</p> <p>This item of plant has attachments that require continued function when the operator is not at the normal operating position. Ensure these function(s) are either -</p> <p>i) automatically deactivated when the machine is switched off and remains deactivated when the machine is switched on, or</p> <p>ii) prevent the machine from being restarted until the function is deactivated.</p> <p>Once achieved operators and maintenance staff MUST NEVER attempt to bypass this important safety feature. Failure to comply with this instruction may lead to serious injury or death.</p> <p>References: AS10896.1</p>						
 ELECTROCUTION	HIGH 22	MEDIUM 15	1 Week	31-Mar-25		
<p>Risk Treatment Required: Electrical Approach Distances</p> <p>Attach a clear hazard warning label re: overhead electrical hazards and minimum approach distances adjacent operator work areas and any access to the top of the item of plant. These distances must be adhered to strictly. Once fitted these labels and tables must be present, clear and legible at all times.</p> <p>Spotters are required when working within 5 metres of the minimum approach distance of any live electrical apparatus.</p> <p>Any encroach within the minimum approach distances must only occur if the following provisions have been met -</p> <ol style="list-style-type: none"> 1. The machine is designed to work within the minimum approach distances 2. Permission has been granted by the electricity company 3. Safe systems of work have been documented and approved <p>Legislation: State Health & Safety Legislation & Regulation</p> <p>References: ISO31000</p>						
 CRUSHING	HIGH 22	MEDIUM 15	1 Week	31-Mar-25		
<p>Risk Treatment Required: ROPS Label</p> <p>Attach hazard warning label stating that the ROPS must not be damaged at any time (including cuts, drill holes and welds). This label must be present, clean and legible at all times.</p> <p>Legislation: State Health & Safety Legislation & Regulation</p> <p>References: AS2294, ISO3471</p>						
 INCORRECT OPERATION	HIGH 22	MEDIUM 15	1 Week	31-Mar-25		
<p>Risk Treatment Required: Control Labels</p> <p>Ensure all controls including all levers, buttons, pedals, switches etc. are clearly labelled as to their purpose and method of operation prior to operating this item of plant. Once achieved these labels must be maintained in a clean condition at all times.</p> <p>Legislation: State Health & Safety Legislation & Regulation</p> <p>References: AS/NZS4024.1905</p>						















HAZARD(S)	Prelim. Risk Rating	Residual Risk Rating	Time Frame	Due Date	Date Rectified	Initial
 COLLISION, CRUSHING	HIGH 22	MEDIUM 15	1 Week	31-Mar-25		
Risk Treatment Required: Loose Items - Operator Work Area Ensure all items that could cause harm to the operator in the event of a collision or rollover are securely restrained.						
References: ISO31000						
 NON COMPLIANCE	HIGH 22	MEDIUM 15	1 Week	31-Mar-25		
Risk Treatment Required: 90 day (quarterly) Routine Inspection Ensure that a 90 day (quarterly) routine inspection is carried out prior to operation. Once completed ensure that these are continually carried out every 90 days.						
References: AS2550.19-						
 CRUSHING, FALLING	HIGH 22	MEDIUM 15	1 Week	31-Mar-25		
Risk Treatment Required: Passenger Seat Label Ensure that a clear hazard warning label re: Operator only, No passengers is fitted to the operator area of this item of plant. Passengers must not be carried at anytime. Once fitted this label must be clear and legible at all times whilst this item of plant is in operation.						
References: AS1319-						
 CRUSHING, NON COMPLIANCE	HIGH 22	MEDIUM 15	1 Week	31-Mar-25		
Risk Treatment Required: Forklift Tyne Movement Lock Ensure that the fork tynes are fitted with a lateral movement locking device. Once fitted this device must be employed and fully functional at all times whilst this item of plant is in use. Always follow manufacturers instructions for adjusting and locking the fork tynes.						
References: AS2359						
 NON COMPLIANCE	HIGH 22	MEDIUM 15	1 Week	31-Mar-25		
Risk Treatment Required: Plant (annual) Periodic Inspection Ensure that this item of plant has an annual periodic inspection which is carried out by a competent person and to determine if this item of plant is safe for use. Documentation to this effect must be available once the inspection is complete. This item of plant must be re-inspected every 12 months by a competent person and new documentation be provided.						
References: AS2550.19-						
 COLLISION, CRUSHING, STRIKING	HIGH 22	MEDIUM 15	1 Week	31-Mar-25		
Risk Treatment Required: Vehicle Frequently Reversing Ensure the rear of this item of plant has a hazard warning label re: vehicle frequently reversing. It must be present and fully functional and serviceable at all times.						
References: AS/NZS4024.1201, AS1319-						
 BURNS, EXPLOSION, POISONING	HIGH 22	MEDIUM 15	1 Week	31-Mar-25		
Risk Treatment Required: Tank ID Label Ensure the tank(s) on this item of plant have clear, legible label(s) identifying their contents, and if appropriate any necessary controls re: the contents. Once attached these must be present, clear and legible at all times. (this includes radiator, hydraulic, water and petrol/diesel tanks etc.) Legislation: State Health & Safety Legislation & Regulation						
References: Occupational Health & Safety Act & Regulations, Work Health & Safety Act & Regulations-						
Assessor Comments: Label missing - hydraulic tank.						





HAZARD(S)	Prelim. Risk Rating	Residual Risk Rating	Time Frame	Due Date	Date Rectified	Initial
 COLLISION	HIGH 22	MEDIUM 15	1 Week	31-Mar-25		
<p>Risk Treatment Required: Left Hand Drive Label</p> <p>Ensure this item of plant has a hazard warning label re: left hand drive, attached to rear prior to operation. It must be present, clear and legible at all times.</p> <p>Legislation: State Health & Safety Legislation & Regulation</p> <p>References: ISO31000</p>						
 COLLISION, CRUSHING	HIGH 22	MEDIUM 15	1 Week	31-Mar-25		
<p>Risk Treatment Required: Reverse Movement Alarm</p> <p>Ensure this item of plant is fitted with a reverse movement awareness alarm which is automatically activated when reverse gear is selected prior to operating this item of plant. Once fitted it must be fully functional and serviceable at all times whilst this item of plant is in operation.</p> <p>References: ISO7731</p>						
 NON COMPLIANCE, OPERATIONAL MALFUNCTION	HIGH 22	MEDIUM 15	1 Week	31-Mar-25		
<p>Risk Treatment Required: Telescopic Handler Load Chart</p> <p>Ensure this item of plant is fitted with clear and legible load chart(s) for each attachment that is in clear view of the operator from the normal operating position containing the following information as a minimum -</p> <ul style="list-style-type: none"> a) the type of attachment to which it applies b) applicable load centre distances c) actual capacities at lift heights and reach d) applicable limitations on the attachment use e) model of the machine to which it applies f) type of tyres g) use with and without stabilising device, if applicable h) use with and without ballasted tyres and optional counterweights, if applicable i) capacities when stabilising devices are deployed and when not deployed. <p>Once fitted this chart and information must be legible at all time whilst this item of plant is in operation.</p> <p>References: AS10896.1</p>						
 CRUSHING	HIGH 22	MEDIUM 15	1 Week	31-Mar-25		
<p>Risk Treatment Required: SWMS Loading/Unloading</p> <p>Source or develop guidelines for loading and unloading this machine to and from a flat top truck or trailer, low loader or tilt tray.</p> <p>Once developed, ensure that all operators follow approved SWMS/SOP when loading and unloading this machine to and from a flat top truck or trailer, low loader or tilt tray.</p> <p>References: Occupational Health & Safety Act & Regulations, Work Health & Safety Act & Regulations-</p>						
 INCORRECT OPERATION	HIGH 22	MEDIUM 15	1 Week	31-Mar-25		
<p>Risk Treatment Required: Pre-op Checklist Telescopic Handler</p> <p>Source or develop pre-operational checklist for this Telescopic Handler. (Pre-op checklist available via the Custom Reports section of Plant Assessor)</p> <p>References: Occupational Health & Safety Act & Regulations, Work Health & Safety Act & Regulations-</p>						
 INCORRECT OPERATION	HIGH 22	MEDIUM 15	1 Week	31-Mar-25		
<p>Risk Treatment Required: SOP Telescopic Handler</p> <p>Source or develop Safe Operation Procedures for this Telescopic Handler. (Safe Operation Procedures are available via the Custom Reports section of Plant Assessor)</p> <p>References: Occupational Health & Safety Act & Regulations, Work Health & Safety Act & Regulations-</p>						
 CRUSHING	HIGH 22	MEDIUM 15	1 Week	31-Mar-25		
<p>Risk Treatment Required: SWMS Load Restraint</p> <p>Source or develop transport restraining guidelines for this machine.</p> <p>Once developed, ensure that all operators follow the approved SWMS/SOP when restraining this machine for transport.</p> <p>References: Occupational Health & Safety Act & Regulations, Work Health & Safety Act & Regulations-</p>						

HAZARD(S)	Prelim. Risk Rating	Residual Risk Rating	Time Frame	Due Date	Date Rectified	Initial
 BURNS, STRIKING	HIGH 22	MEDIUM 15	1 Week	31-Mar-25		
<p>Risk Treatment Required: Hydraulic Damage</p> <p>The hydraulic hoses to this item of plant must be free from damage and have protection against damage arising from contact with the plant structure. Replacement hoses or protection must be installed as per the time frame above. Once installed, ensure that hoses and protection are in place at all times whilst this item of plant is in operation. Inspection of the hoses and protection should be conducted regularly and documented as part of your plant safety programme.</p> <p>Legislation: State Health & Safety Legislation & Regulation</p> <p>References: AS2671, AS4024, ISO4413</p> <p>Assessor Comments: Ensure that all hydraulic hoses are inspected and any damaged hoses are replaced and secured correctly by a competent person prior to operation.</p>						
 INCORRECT OPERATION	HIGH 22	MEDIUM 15	1 Week	31-Mar-25		
<p>Risk Treatment Required: Maintenance Manual</p> <p>The manufacturer's maintenance manual(s) are not available for this item of plant</p> <p>These manuals must be sourced and made freely available to all persons carrying out maintenance activities as a requirement of current legislation. If these manuals cannot be sourced, the maintenance manual(s) must be developed by a competent person, and then made available to all relevant persons.</p> <p>Legislation: State Health & Safety Legislation & Regulation</p> <p>References: AS10896.1, Occupational Health & Safety Act & Regulations, Work Health & Safety Act & Regulations-</p>						
 INCORRECT OPERATION	HIGH 22	MEDIUM 15	1 Week	31-Mar-25		
<p>Risk Treatment Required: Operation Handbook</p> <p>The manufacturer's operation handbook is not available for this item of plant. A full assessment of the competence of operators must also be undertaken.</p> <p>This handbook must be sourced and made available to all operators and maintenance staff at all times as a requirement of current legislation. If Operation handbook cannot be sourced the operation manual must be developed by a competent person. All personnel who may operate this item of plant must read and be familiar with this handbook prior to operating.</p> <p>Legislation: State Health & Safety Legislation & Regulation</p> <p>References: Occupational Health & Safety Act & Regulations, Work Health & Safety Act & Regulations-</p>						
 NON COMPLIANCE	HIGH 22	MEDIUM 15	1 Week	31-Mar-25		
<p>Risk Treatment Required: Telescopic Handler Major Inspection</p> <p>This item of plant is not to be used until a major inspection is conducted. Once conducted certification is only valid for a further 5 years.</p> <p>References: AS2550.19-</p> <p>Assessor Comments: DOM 03/2007 - major inspection overdue.</p>						
 CRUSHING, INCORRECT OPERATION	HIGH 22	MEDIUM 15	1 Week	31-Mar-25		
<p>Risk Treatment Required: Longitudinal Load Moment Control</p> <p>This item of plant must be fitted with a fully functional longitudinal load moment control (LLMC). This system restricts further motion of the load which increases longitudinal instability beyond the allowable limit(s)). Operation of this item of plant must cease if this safety device is not present and fully functional.</p> <p>References: AS10896.1</p>						
 CRUSHING, INCORRECT OPERATION	HIGH 22	MEDIUM 15	1 Week	31-Mar-25		
<p>Risk Treatment Required: Longitudinal Load Moment Indicator</p> <p>This item of plant must be fitted with a fully functional longitudinal load moment indicator (LLMI). This indicator must continuously warn both visually and audibly when the load has increased the longitudinal load moment beyond its predetermined limit(s).</p> <p>Once fitted this warning must not be ignored. Operators must immediately take the appropriate actions to decrease longitudinal instability. This item of plant must not be operated if this device is not present and fully functional.</p> <p>References: AS10896.1</p>						



HAZARD(S)	Prelim. Risk Rating	Residual Risk Rating	Time Frame	Due Date	Date Rectified	Initial
 CRUSHING, INCORRECT OPERATION	HIGH 22	MEDIUM 15	1 Week	31-Mar-25		
<p>Risk Treatment Required: Boom Length Indicator</p> <p>This item of plant must be fitted with a telescopic boom length indicator. The information provided by this device must be used in conjunction with the boom angle indicator and the load chart in the operators work area. The combination of information provided by these safety features must not be exceeded at any time during operation. This item of plant must not be operated if this device is not present and fully functional.</p> <p>References: AS10896.1</p>						
 CUTTING, ENTANGLEMENT, SHEARING	HIGH 22	MEDIUM 15	1 Week	31-Mar-25		
<p>Risk Treatment Required: Emergency Stop Device</p> <p>This item of plant must be fitted with an emergency stop device which meets the following criteria prior to operation.</p> <ol style="list-style-type: none"> 1. Is operational 2. Is coloured red with yellow background 3. Is clearly labeled as to purpose and method of operation 4. Is easily accessible to the operator(s) at all times whilst operating this item of plant 5. Resetting of emergency stop does not automatically restart machine 6. Is located at each operator control station 7. Be designed to - <ul style="list-style-type: none"> - Not impair the effectiveness of other safety functions - Note: it can be necessary to ensure the continuing operation of auxiliary equipment such as steering & braking devices - Be so designed, that after actuation of the emergency stop device, hazardous movements and operations of the machine are stopped in an appropriate manner without creating additional hazards and without further intervention - Note: appropriate manner can include optimal deceleration rate or necessity for predetermined shutdown sequence and so on - A risk assessment must be conducted to confirm that no additional hazards have been created - More than one emergency stop may be required - Be a complimentary protective measure and shall not be applied as a substitute for safeguarding measures and other functions or safety measures - Be designed so that a decision to activate the emergency stop device does not require the consideration of the resultant effects <p>Once fitted it must be serviceable at all times whilst this item of plant is in operation. All operators must be familiar with the use and effects of actuation of the emergency stop device.</p> <p>References: AS/NZS4024.1604</p>						
 COLLISION	HIGH 22	MEDIUM 15	1 Week	31-Mar-25		
<p>Risk Treatment Required: Phone Use label</p> <p>This item of plant must be fitted with an instruction label advising that mobile phones must not be used whilst operating this machine. Accordingly all operators must not use a mobile phone at any time whilst operating machine. If phone use is necessary then operator must place machine in park configuration in a safe position prior to phone use. Operators MUST adhere to this advice at all times.</p> <p>Once fitted this label must be clear and legible at all times whilst this item of plant is in operation.</p> <p>References: AS1319- , ISO31000</p>						
 NON COMPLIANCE, OPERATIONAL MALFUNCTION	HIGH 21	MEDIUM 15	1 Week	31-Mar-25		
<p>Risk Treatment Required: Log Book</p> <p>Ensure that this item of plant has a log book available on the item of plant at all times and that the book contains an up to date record of the service, maintenance, pre-op checks and use of this item of plant.</p> <p>References: AS2550.19-</p>						
 ENTRAPMENT	HIGH 21	MEDIUM 15	1 Week	31-Mar-25		
<p>Risk Treatment Required: Emergency Exits</p> <p>Ensure the emergency exits for this item of plant meet the following requirements -</p> <ol style="list-style-type: none"> 1. Clearly and legibly labelled 2. Instructions for use are clear and legible and located adjacent the exit 3. Any required tools required for use are available e.g. Emergency hammers <p>These exits must be legibly labelled and fully functional at all times whenever the item of plant is manned, whether during operation or maintenance activities.</p> <p>References: AS10896.1, ISO31000</p>						








HAZARD(S)	Prelim. Risk Rating	Residual Risk Rating	Time Frame	Due Date	Date Rectified	Initial
 COLLISION, CRUSHING	HIGH 21	MEDIUM 15	1 Week	31-Mar-25		
<p>Risk Treatment Required: Park Brake Warning</p> <p>Ensure this item of plant fitted with a fully functional alarm to warn the operator when leaving the operator's position if the park brake is not applied.</p> <p>Once fitted this alarm must be fully functional at all times whilst this item of plant is in operation.</p> <p>References: AS10896.1</p>						
 NON COMPLIANCE	HIGH 21	MEDIUM 15	1 Week	31-Mar-25		
<p>Risk Treatment Required: Boom Hazard Warning Label</p> <p>Ensure this item of plant is fitted with a clear and legible hazard warning label that is in clear view of the operator from the normal operating position re: machine is to be level before lifting or extending the boom?</p> <p>Once fitted this hazard warning label must be clear and legible at all times whilst this item of plant is in operation.</p> <p>References: AS10896.1</p>						
 FIRE	HIGH 21	MEDIUM 15	1 Week	31-Mar-25		
<p>Risk Treatment Required: Fire Extinguisher</p> <p>No fire extinguishers are installed on this item of plant. Fire extinguisher(s) to AS 1841 must be present and fully functional and serviceable at all times. They must be readily accessible to the operator. Regular inspections must also be carried out in accordance with the manufacturer's requirements and AS 1851</p> <p>Legislation: State Health & Safety Legislation & Regulation</p> <p>References: AS10896.1, AS1851</p>						
 OPERATIONAL MALFUNCTION	HIGH 21	MEDIUM 15	1 Week	31-Mar-25		
<p>Risk Treatment Required: Service Records</p> <p>Service and maintenance records are not available for this item of plant.</p> <p>This risk assessment will form the basis of your records for this item of plant. Service and maintenance records must be developed, managed and made available at all times as part of your plant safety management programme. (This programme includes the undertaking of regular inspections of the item of plant with specific reference to all OEM prescribed, scheduled and non scheduled service and maintenance requirements).</p> <p>Legislation: State Health & Safety Legislation & Regulation</p> <p>References: Occupational Health & Safety Act & Regulations, Work Health & Safety Act & Regulations-</p>						
 INCORRECT OPERATION	HIGH 20	MEDIUM 14	1 Week	31-Mar-25		
<p>Risk Treatment Required: Intuitive Controls</p> <p>The controls fitted to this item of plant must be orientated so that the movement of the control is consistent with the action of the machine e.g. moving a control lever to the left results in the machine turning to the left.</p> <p>Once achieved this design feature must be maintained at all times whilst this item of plant is in operation.</p> <p>References: AS/NZS4024.1906</p>						
 INCORRECT OPERATION, SLIPPING	HIGH 17	LOW 6	1 Week	31-Mar-25		
<p>Risk Treatment Required: Control Levers/Pedals/Buttons</p> <p>Ensure all controls including all levers, buttons, pedals, switches etc. are non-slip and free from damage prior to operating this item of plant. These conditions must be maintained to this level at all times whilst operating this item of plant.</p> <p>Legislation: State Health & Safety Legislation & Regulation</p> <p>References: AS/NZS4024.1901</p>						
 BURNS, ENTANGLEMENT, SHEARING	MEDIUM 14	MEDIUM 13	1 Month	23-Apr-25		
<p>Risk Treatment Required: Engine Guard Label</p> <p>Ensure all engine guards have a hazard warning label which states that the guard must not be opened unless the engine is not running and all moving parts behind have stopped. These labels must be present and fully functional and serviceable at all times whilst this item of plant is in operation.</p> <p>Legislation: State Health & Safety Legislation & Regulation</p> <p>References: AS/NZS4024.1201, AS1319-</p>						









HAZARD(S)	Prelim. Risk Rating	Residual Risk Rating	Time Frame	Due Date	Date Rectified	Initial
 COLLISION, CRUSHING	MEDIUM 12	LOW 6	1 Month	23-Apr-25		
<p>Risk Treatment Required: Warning Device (horn)</p> <p>Ensure that this item of plant is fitted with a fully functional audible warning device such as a horn. Once installed this must be easily accessed by the operator, and easily identifiable by nearby pedestrians.</p> <p>Once installed, Operators should ensure the warning devices are functional at the start of each shift, by completing pre-start checklists. Warning devices should operate automatically where appropriate (eg reversing)</p> <p>Legislation: State Health & Safety Legislation & Regulation</p> <p>References: AS10896.1, ISO7731</p>						
 FALLING, SLIPPING	MEDIUM 12	LOW 6	1 Month	23-Apr-25		
<p>Risk Treatment Required: Access/Egress Instruction Label</p> <p>Ensure the access and egress to the cabin/work area has an instruction label fitted with the following information as a minimum -</p> <p>All personnel must -</p> <ol style="list-style-type: none"> 1. Always face the item of plant during access and egress. 2. Always maintain three points of contact during access and egress. 3. Ensure the steps are clean. 4. Never jump off machine. <p>Once fitted this label must be clear and legible at all times whilst this item of plant is in operation.</p> <p>References: ISO31000</p>						








SECTION 5 RISK TREATMENTS IN PLACE









This section of the report pertains to risk treatments currently in place on this item of plant. This section must be read in conjunction with the safety section of the manufacturers handbook. All operators must read and understand the entire contents of this section prior to operating this item of plant. These treatments or equivalent must remain in place at all times whilst this item of plant is in operation.









HAZARD(S)	Prelim. Risk Rating	Residual Risk Rating
 COLLISION, INSTABILITY	HIGH 22	MEDIUM 15
<p>Risk Treatment In Place: Tyres</p> <p>The tyres and wheel components must be inspected as part of a "pre start" checklist. These inspections must be documented as part of your plant safety programme.</p> <p>References: ISO31000</p>		
 BURNS, STRIKING	HIGH 22	MEDIUM 15
<p>Risk Treatment In Place: Hydraulic Hoses</p> <p>This item of plant has hydraulic hoses. These hoses must be inspected each day or before each use for wear and tear. If there are visible signs of wear, immediate action must be taken to control the risk arising from this wear. These inspections must be documented.</p> <p>Hydraulic fluid at high pressure can penetrate the skin, never use any part of your body to check for leaks. If oil penetrates the skin seek medical advice immediately. Always use a piece of cardboard or similar to check for suspected leaks. Always wear appropriate gloves when handling hydraulic hoses.</p> <p>Hydraulic pressure can be stored and is a hazard. Always connect and disconnect hydraulic hoses as per the manufacturer's manual.</p> <p>References: AS2671, AS4024</p>		


HAZARD(S)		Prelim. Risk Rating	Residual Risk Rating
 INCORRECT OPERATION, NON COMPLIANCE		HIGH 22	MEDIUM 15
<p>Risk Treatment In Place: Fork Attachment</p> <p>This item of plant is fitted with a fork attachment. This attachment must be inspected as part of the daily pre start check or before each use.</p> <p>For safe operation of this attachment ensure all operators are familiar with at least the following as a minimum;</p> <p>Training: Ensure operators are qualified, trained and experienced in the use of this attachment. Inspection: Regularly inspect attachments for any signs of wear or damage. This includes checking for cracks, bends, or other deformities. Compatibility: Ensure the attachment is compatible with the carrier unit. Load Capacity: Be aware that attachments can alter the carrier unit's load capacity and center of gravity. Never exceed manufacturer's rated capacity. Stability: Use attachments on level ground to maintain stability and prevent tipping. Visibility: Attachments can affect the operator's visibility. Ensure the operator has a clear view of their surroundings, always carry the load as low as possible. Attaching: Follow the manufacturer's instructions for coupling and uncoupling of the attachment.</p> <p>Ensure that fork tynes are of sufficient length to support 75% of the load, fork tynes should be spread apart as wide as practicable so that the load is stable and evenly distributed on both fork tynes to ensure stability of the load prior to lifting.</p> <p>References: ISO31000</p>			
 SLIPPING		MEDIUM 12	LOW 6
<p>Risk Treatment In Place: Operator Work Area Access/Egress</p> <p>Safe access and egress to the cabin/work area(s) must be maintained at all times whilst this item of plant is in operation. It must be non slip, free from damage, located at a height so as to not cause undue body stresses and strains with three points of contact available to personnel at all times.</p> <p>All personnel must -</p> <ol style="list-style-type: none"> 1. Always face the item of plant during access and egress. 2. Always maintain three points of contact during access and egress. 3. Never carry an object(s) in his/her hand(s) during access and egress. 4. Never jump off machine. <p>References: AS10896.1, AS1657</p>			
 STRAINS		HIGH 19	LOW 5
<p>Risk Treatment In Place: Controls Ergonomics</p> <p>All controls including all levers, buttons, pedals, switches etc, are placed near the operator work position and are easy to reach and operate during the execution of the operator's normal duties. This applies for all persons within the 95th percentile of the normal population distribution.</p> <p>References: AS/NZS4024.1901</p>			
 ENTRAPMENT		HIGH 21	MEDIUM 15
<p>Risk Treatment In Place: Two Operator Exits</p> <p>The operator cabin/work area on this item of plant has a minimum of two (2) possible exits. These must be functional and accessible at all times whenever the item of plant is manned, whether during operation or maintenance activities.</p> <p>References: AS10896.1, AS1418.1</p>			
 COLLISION, POOR VISIBILITY		HIGH 21	MEDIUM 15
<p>Risk Treatment In Place: Windows & Screens</p> <p>Ensure the cabin/work area safety glass windows and screens are kept clean and free from cracks and other damage at all times whilst this item of plant is in use.</p> <p>References: AS/NZS4024.1201, AS1418.1</p>			
 COLLISION, CRUSHING, ENTANGLEMENT, STRIKING		HIGH 22	MEDIUM 15
<p>Risk Treatment In Place: Neutral Start</p> <p>This item of plant has neutral start control in place. It must be fully functional and serviceable at all times whilst this item of plant is in operation.</p> <p>References: AS10896.1, AS4024.1603</p>			
 COLLISION, CRUSHING		CRITICAL 24	MEDIUM 15
<p>Risk Treatment In Place: Hold To Run Controls</p> <p>This item of plant is fitted with "hold to run" type controls. Operators and maintenance staff MUST NEVER attempt to bypass this important safety feature. Failure to comply with this instruction may lead to serious injury or death.</p> <p>References: AS/NZS4024.1906, AS10896.1</p>			

HAZARD(S)	Prelim. Risk Rating	Residual Risk Rating
 INCORRECT OPERATION, SLIPPING	MEDIUM 9	LOW 4
<p>Risk Treatment In Place: Work Area Floors</p> <p>All work area floors are non-slip and free from damage & debris.</p> <p>Floor area must remain non-slip and free from damage & debris, including rubbish, tools and other items, at all times whilst this item of plant is in use.</p> <p>References: AS/NZS4024.1201</p>		
 COLLISION, POOR VISIBILITY	HIGH 22	MEDIUM 15
<p>Risk Treatment In Place: Operator Mirrors</p> <p>The operator rear view mirrors fitted to this item of plant must be fully functional and kept clean at all times. There must always be at least one mirror on each side to provide rear vision to the operator to avoid striking bystanders and objects.</p> <p>References: AS/NZS4024.1201, AS1418.1</p>		
 NON COMPLIANCE, STRAINS	MEDIUM 9	LOW 1
<p>Risk Treatment In Place: Operator Seat</p> <p>The operator seat fitted to this item of plant must remain free from damage and tears, and be permanently and securely fitted at all times.</p> <p>References: AS/NZS4024.1401 , AS10896.1, AS1418.1</p>		
 CRUSHING	CRITICAL 24	MEDIUM 15
<p>Risk Treatment In Place: Manual Hitch</p> <p>This item of plant is fitted with a manual hitch that meets the following requirements -</p> <ol style="list-style-type: none"> 1. Has a primary retention system and a secondary safety system fitted 2. The primary retention system must be engaged and disengaged at the hitch 3. The secondary safety system must be retained on the hitch so that it cannot be removed without the use of tools. <p>These requirements must be met at all times whilst this item of plant is in operation.</p> <p>References: AS13031</p>		
 CRUSHING	HIGH 22	MEDIUM 15
<p>Risk Treatment In Place: Seat Belt</p> <p>This item of plant is fitted with an operator seat belt. This seat belt must be free from damage, and permanently and sturdily attached at all times whilst this item of plant is in operation. Operators must use this seat belt at all times during operation.</p> <p>References: AS/NZS4024.1201, AS10896.1</p>		
 COLLISION, POOR VISIBILITY	HIGH 21	MEDIUM 15
<p>Risk Treatment In Place: Windscreen Wipers</p> <p>The windscreen wipers and washers fitted to this item of plant must be fully functional at all times.</p> <p>References: AS/NZS4024.1201, AS10896.1</p>		
 DEHYDRATION, HEAT STROKE	MEDIUM 9	LOW 4
<p>Risk Treatment In Place: Air Conditioning</p> <p>This item of plant is fitted with an air conditioned cabin. This air conditioned cabin helps control the air quality and temperature for the operator and also provides shade from the sun. The air conditioner must be fully functional and serviceable at all times whilst this item of plant is in operation.</p> <p>References: ISO31000</p>		
 COLLISION, CRUSHING	CRITICAL 25	MEDIUM 15
<p>Risk Treatment In Place: Brakes</p> <p>The brakes fitted to this item of plant must be fully functional at all times whilst this item of plant is in operation. The brakes must be regularly inspected and tested. These inspections and tests must be documented as part of your plant safety programme.</p> <p>References: AS10896.1, ISO31000</p>		

HAZARD(S)	Prelim. Risk Rating	Residual Risk Rating
 COLLISION, CRUSHING	CRITICAL 24	MEDIUM 15
<p>Risk Treatment In Place: Park Brake</p> <p>This item of plant is fitted with a fully functional park (hand) brake which meets the following requirements –</p> <ol style="list-style-type: none"> 1. Is separate to the service brakes 2. Has a device which maintains the brake in the on position until intentionally disengaged <p>The park brake must be regularly inspected and tested. These inspections and tests must be documented as part of your plant safety programme.</p> <p>References: ISO31000</p>		
 INCORRECT OPERATION, OPERATIONAL MALFUNCTION	MEDIUM 14	MEDIUM 13
<p>Risk Treatment In Place: Restricted Access Switches</p> <p>This item of plant is fitted with a device to restrict operators. A code/key must only be given to those that have appropriate experience or training.</p> <p>References: AS10896.1</p>		
 NON COMPLIANCE	HIGH 21	MEDIUM 15
<p>Risk Treatment In Place: Telescopic Handler Manufacturer Plate</p> <p>This item of plant is fitted with a manufacturer supplied plate which contains the following information as a minimum –</p> <ol style="list-style-type: none"> a) business name and full address of the manufacturer or authorised representative b) designation of series or type c) serial number d) year of construction e) rated capacity f) net power of engine expressed in kilowatts (kW) g) mass of the unladen truck, fully fuelled and serviced, without the operator and without the mass of any removable attachment h) if necessary, the maximum vertical force and the drawbar pull on the tow-hook in newtons (N). <p>This plate must be clean and legible at all times whilst this item of plant is in operation.</p> <p>References: AS10896.1</p>		
 CRUSHING	HIGH 22	MEDIUM 15
<p>Risk Treatment In Place: Earthmoving ROPS</p> <p>A Roll Over Protective Structure (ROPS) to AS 2294, ISO 3471, ISO 12117.1 or 2 or SAE J1040 is fitted to this item of plant. A permanent label stating this standard must be attached to the structure at all times. It must also carry a warning label re: wearing of seat belts at all times whilst this item of plant is in operation, and accordingly seat belts must be worn at all times during operation.</p> <p>References: AS2294, ISO3471</p>		
 CRUSHING	HIGH 22	MEDIUM 15
<p>Risk Treatment In Place: ROPS Damage</p> <p>The Roll Over Protective Structure (ROPS) fitted to this item of plant must remain free from damage at all times whilst this item of plant is in operation.</p> <p>References: AS2294, ISO3471</p>		
 CRUSHING, INCORRECT OPERATION	HIGH 22	MEDIUM 15
<p>Risk Treatment In Place: Longitudinal Stability Indications</p> <p>This item of plant is fitted with a device to indicate to the operator that the maximum limit of longitudinal stability has been reached. Operators must immediately take the appropriate actions to decrease longitudinal instability. This item of plant must not be operated if this device is not present and fully functional.</p> <p>References: AS10896.1</p>		
 CRUSHING	HIGH 22	MEDIUM 15
<p>Risk Treatment In Place: ROPS seat belt label</p> <p>This item of plant is fitted with a ROPS and has an advisory label stating that "seatbelts must be worn". This label must be present, clean and legible at all times. All operators and passengers must wear seatbelts whilst on this item of plant.</p> <p>References: AS2294, ISO3471</p>		

HAZARD(S)	Prelim. Risk Rating	Residual Risk Rating
 NON COMPLIANCE	MEDIUM 14	LOW 6
Risk Treatment In Place: Engine/Motor Compartment The engine/motor compartment is fully enclosed and lockable to prevent unauthorised access. A code/key must only be given to those that have appropriate experience or training. These points of access must remain fully lockable at all times whilst this item of plant is in operation. References: AS10896.1		
 CRUSHING, INCORRECT OPERATION	HIGH 22	MEDIUM 15
Risk Treatment In Place: Slope Indicators This item of plant is fitted with a lateral and longitudinal slope indicator. These indicators must always be easily legible from the normal operating position and indicate level and permitted lateral and longitudinal slope as specified by the rated capacity chart. The maximum permissible lateral and longitudinal slope must not be exceeded at anytime during operation of this item of plant. Operation of this item of plant other than on level ground must cease if these devices are not present and fully functional. References: AS10896.1		
 CRUSHING	HIGH 21	LOW 5
Risk Treatment In Place: FOPS Level II - Telehandler This item of plant is fitted with a level II Falling Objects Protective Structure (FOPS). This structure is designed to protect the operator from heavy falling objects (e.g. trees, rocks). Care should still be exercised when operating in an area with a risk of falling objects. References: AS10896.1, ISO3449		
 COLLISION, POOR VISIBILITY	HIGH 22	MEDIUM 15
Risk Treatment In Place: Machine Lights This item of plant is fitted with self contained lighting. All of these lights must be fully functional and serviceable whilst this item of plant is in operation in areas of reduced light. If any of these lights stop working the operation must cease immediately and the faulty light be repaired before operation can continue in the areas of reduced light. References: AS/NZS4024.1201, AS10896.1		
 CRUSHING	HIGH 22	LOW 2
Risk Treatment In Place: Hydraulic Load Holding Devices The load carrying cylinders on this item of plant are fitted with automatic means (e.g. load-holding valves) to prevent uncontrolled movement of the unit in the case of loss of power or hydraulic failure. These devices must be present and fully functional at all times whilst this item of plant is in operation. References: AS10896.1, AS1418.1		
 ENTANGLEMENT	HIGH 22	MEDIUM 15
Risk Treatment In Place: Engine Guards The engine fan and alternator belts, pulleys and gears are guarded. These guards must be present and fully functional and serviceable at all times whilst this item of plant is in operation. References: AS/NZS4024.1601, AS10896.1		
 BURNS	MEDIUM 9	LOW 5
Risk Treatment In Place: Exhaust The engine exhaust on this item of plant is fitted with a guard to prevent injury to any person and control the risk of initiating a fire. It must be present and fully functional and serviceable at all times whilst this item of plant is in operation. References: AS/NZS4024.1201, AS10896.1		
 CRUSHING	HIGH 21	MEDIUM 15
Risk Treatment In Place: Loader Crush Zone Label The loader boom on this item of plant is fitted with a hazard warning label re: crush zone, keep clear. This label must be present and fully functional and serviceable at all times. References: AS1319-		

HAZARD(S)	Prelim. Risk Rating	Residual Risk Rating
 BURNS, ELECTRIC SHOCK	MEDIUM 12	LOW 6
Risk Treatment In Place: Battery Cover All batteries fitted to this item of plant are constrained to prevent displacement & fitted with a permanent sturdy cover which allows for ventilation. The constraint and cover must be present and fully functional and serviceable at all times whilst this item of plant is in operation.		
References: AS/NZS4024.1201, AS10896.1		
 OPERATIONAL MALFUNCTION	HIGH 22	LOW 2
Risk Treatment In Place: Major Fluid Leaks This item of plant must remain free from leaks at all times whilst in operation (this includes engine, transmission, cooling system, air, fuel, drive line, wheel hubs, steering and hydraulics). Development of a major leak will require this item of plant to be stood-down until repaired. Minor leaks detected must be repaired within 1-14 days.		
References: ISO31000		
 FIRE, NON COMPLIANCE	MEDIUM 12	LOW 6
Risk Treatment In Place: Battery Disconnection This item of plant is fitted with a device that enables quick disconnection of the batteries which is clearly labelled as to its purpose and method of operation. This device must be fully functional and clearly labelled at all times whilst this item of plant is in operation.		
References: AS10896.1		
 CRUSHING, INSTABILITY	HIGH 21	MEDIUM 15
Risk Treatment In Place: Rated Capacity (SWL) Label This item of plant has a rated capacity (SWL) label. This capacity must not be exceeded at any time during operation. This label must be clear and legible at all times whilst this item of plant is in operation.		
References: AS1418.1		
 COLLISION	HIGH 22	MEDIUM 15
Risk Treatment In Place: Beacon This item of plant is fitted with a safety beacon. This beacon must meet the following criteria at all times whilst this item of plant fitted is in operation - - Is visible up to 200m in all directions (allowing for intermittent obstruction from the plant structure whilst the plant is in operation) - Is fitted in the most appropriate location on machine to maximise visibility without risking continual damage NOTE: more than one beacon may be fitted to meet these criteria.		
References: AS/NZS4024.1201		
 CRUSHING, INCORRECT OPERATION	HIGH 22	MEDIUM 15
Risk Treatment In Place: Manual Boom Angle Indicator This item of plant is fitted with a boom angle indicator. The information provided by this device must be used in conjunction with the boom length indicator and the load chart in the operators work area. The combination of information provided by these safety features must not be exceeded at any time during operation. This item of plant must not be operated if this device is not present and fully functional.		
References: AS10896.1, AS1418.1		
 CRUSHING	HIGH 22	LOW 5
Risk Treatment In Place: Lift Tynes The fork tynes fitted to this item of plant are free from structural damage including deformation. If at anytime the fork tynes do become damaged including deformation then operation must cease and a competent person carry out the necessary repairs prior to operating item of plant again.		
References: AS2359		
 OPERATIONAL MALFUNCTION	HIGH 22	LOW 2
Risk Treatment In Place: Plant Modification The plant is in original condition.		
References: ISO31000		

HAZARD(S)	Prelim. Risk Rating	Residual Risk Rating
 CURRENT OR PREVIOUS STRUCTURAL DAMAGE	CRITICAL 25	MEDIUM 15
Risk Treatment In Place: Structural Integrity Regular checks for structural damage must be undertaken. Look for cracks in frames/chassis (current or repaired), bends or damage to structural components, etc.		
References: ISO31000		

SECTION 6 IMAGES AND NOTES

Due to the location of this item and the timing of the sale, we have been unable to physically attend its location and conduct a full inspection of the machine in person. This report has been compiled using information and photographs provided by Pickles Auctions. It has been completed as accurately as possible using the information provided. It is possible that some inaccuracies may exist in the report. To ensure you have a complete and accurate assessment, we would like to offer the successful purchaser a complimentary self-assessment of this machine using our unique and unrivalled software, Plant Assessor. To claim your free assessment, please contact us on 1300 728 852.



RISK MANAGEMENT REPORT

TYPE	Telescopic Handler	Report Number	PA 20250324-1212
MAKE	JLG	Date	24-Mar-2025
MODEL	3509	Created By	Nathan Harrod
CHASSIS / VIN	YC500001160002762	Assessor	Nathan Harrod
Assist. Assessor(s)			
Owner		Pickles Auctions Brisbane	
Stock Number		61863687	
Sale ID		9579	
Assessment Purpose		Sale	
State		QLD	

PURCHASER ACKNOWLEDGEMENT

I the undersigned acknowledge that I have read and understand the risk management report described above. I also acknowledge that I have received a copy of this risk management report. I also acknowledge that I am authorised to sign on behalf of the purchaser.

Name _____

Company Name _____

Position _____

Signature _____

Date _____

The manufacturer's operational & maintenance handbooks have been supplied,
(circle one) YES NO (initial) _____

Please transfer this assessment to my Plant Assessor membership as a (circle one) HIRE / PLANT IN USE assessment.
My Plant Assessor username is _____

PA 20250324-1212

Thursday, 27 Mar 2025 01:44 PM



Make JLG
Model 3509
Type Telescopic Handler

Chassis / VIN
Assessed By
Date

YC500001160002762
Nathan Harrod
24-Mar-2025